

Tuesday, March 28, 2017 3:41:09 PM

Item ID:	D412-758-015	Accept	*N900040100*	Setup	Start	*NS1*
Revision ID:						
Item Name:	GPS Receiver Gimbal Mount				Stop	*NS2*
Start Date:	3/29/2017	Start Qty:	1.00	*1*	Cust Item ID:	
Required Date:	4/3/2017	Req'd Qty:	1.00	*1*	Customer:	
Reference:	SCHEDULED/C					

Approvals: **Process Plan:** umf **Date:** 17-3-20 **Tooling:** _____ **Date:** _____
 QC: _____ **Date:** _____ **SPC (Y/N):** _____ **Date:** _____

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY		
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐				

Tuesday, March 28, 2017 3:41:09 PM

Page 2

Accept

N900040100

Setup Start *NS1*

Stop *NS2*

Item Name: GPS Receiver Gimbal Mount

Start Date: 3/29/2017 **Start Qty:** 1.00

1

Cust Item ID:

Required Date: 4/3/2017 Req'd Qty: 1.00

1

Customer:

Reference: SCHEDULED/C

Approvals: **Process Plan:** _____ **Date:** _____ **Tooling:** _____ **Date:** _____

Run Start *NR1*

QC: _____ **Date:** _____ **SPC (Y/N):** _____ **Date:** _____

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120

0.00

120

Packaging

0.00

Packaging

Memo

Packaging

Identify and pack for shipping as per PPP D412-758-015

Location:FG023

130

QC21- Final Inspection - Work Order Release

0.00

130

QC

Memo

0.10

Quality Control

DAS
28
9-8

MAR 31 2017

DAS
21
9-89

APR 03 2017

DAS
21
9-89

APR 03 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

Picklist Print

Tuesday, March 28, 2017 3:41:08 PM

Page 1

Work Order ID: 158660

158660

Parent Item: D412-758-015

D412-758-015

Parent Item Name: GPS Receiver Gimbal Mount

Start Date: 3/29/2017

Required Date: 4/3/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev:A 10.06.21 new issue DD verified by:EC
12.10.24 ECN 12-669 DD VERF:JLM

IPP REV:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN525-10R9

Purchased

No

110

Each

167.0000

3

3

AN525-10R9

Screw

**

MAR 30 2017

Location

Loc Qty

Loc Code

ST329

167

m133990

167

D3531-041

Manufactured

No

110

Each

0.0000

1

1

D3531-041

Top Mounted Gps Bracket Assembly

**

158136 MAR 30 2017

D2464

Manufactured

No

110

f

721.8998

1.1

1.157895

D2464

Neoprene Seal (\$per foot)

**

MAR 30 2017

Location

Loc Qty

Loc Code

ST409

721.8998433

121946

721.899843

cut qty of 2 at 6.6" as per dwg D2464-0066 ***per
kit***

D3525-1

Manufactured

No

110

Each

1.0000

1

1

D3525-1

Placard

**

MAR 30 2017

Location

Loc Qty

Loc Code

Mezz

1

140393

1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Tuesday, March 28, 2017 3:41:08 PM

Page 2

Work Order ID: 158660

158660

Parent Item: D412-758-015

D412-758-015

Parent Item Name: GPS Receiver Gimbal Mount

Start Date: 3/29/2017

Required Date: 4/3/2017

Start Qty: 1.00

Required Qty: 1.00

D3645-1

Manufactured No

110

Each

67.0000

4

4

D3645-1

Washer

**

MAR 30 2017

DAS 27
6 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

ST048

67

123144

67

AN525-10R10

Purchased No

110

Each

288.0000

4

4

AN525-10R10

Screw

**

MAR 30 2017

DAS 27
6 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

ST329

288

m135979

288

NAS1149DN632J

Purchased No

110

Each

318.0000

4

4

NAS1149DN632.J

Washer

**

MAR 30 2017

DAS 27
6 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

ST265

318

m134370

318

NAS1149D0363J

Purchased No

110

Each

1,462.000

7

7

NAS1149D0363.J

Washer

**

MAR 30 2017

DAS 27
6 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

GA

106

m134055

106

ST260a

100

m137061

100

ST263

1256

m136781

256

m137164

1000

Tuesday, March 28, 2017 3:41:08 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : _____									

Picklist Print

Tuesday, March 28, 2017 3:41:08 PM

Page 3

Work Order ID: 158660

158660

Parent Item: D412-758-015

D412-758-015

Parent Item Name: GPS Receiver Gimbal Mount

Start Date: 3/29/2017

Required Date: 4/3/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L06

Purchased

No

110

Each

134.0000

4 4

MS21042L06

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

OVER007

50

m137061

50

ST303

84

m136741

84

MS24693-S29

Purchased

No

110

Each

100.0000

4 4

MS24693-S29

SCREW

DAS
28
9-89

Location

Loc Qty

Loc Code

ST286

100

m136741

100

RAM-B-201U-A

Manufactured

No

110

Each

5.0000

2 2

RAM-B-201U-A

Socket Arm, 1.75"

DAS
28
9-89

Location

Loc Qty

Loc Code

ST570

5

144961

5

RAM-B-202U

Manufactured

No

110

Each

4.0000

2 2

RAM-B-202U

Round Plate Mount, Single 1" Ball

DAS
28
9-89

Location

Loc Qty

Loc Code

ST571

4

144972

4

MAR 30 2017

DAS
6
9-89

DAS
27
9-89

MAR 30 2017

DAS
6
9-89

DAS
27
9-89

MAR 30 2017

DAS
6
9-89

DAS
27
9-89

MAR 30 2017

DAS
6
9-89

DAS
27
9-89

Tuesday, March 28, 2017 3:41:09 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Tuesday, March 28, 2017 3:41:09 PM

Page 4

Work Order ID: 158660

158660

Parent Item: D412-758-015

D412-758-015

Parent Item Name: GPS Receiver Gimbal Mount

Start Date: 3/29/2017

Required Date: 4/3/2017

Start Qty: 1.00

Required Qty: 1.00

RAM-B-217U

Manufactured No

110

Each

4.0000

1 1

RAM-B-217U

Round Plate Mount, Dual 1" Ball

DAS
28
9-89

**

MAR 30 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST571

4

144973

4

MS21042L3

Purchased

No

110

Each

1,610.000

3 3

MS21042L3

Nut

DAS
28
9-89

**

MAR 30 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

100

m135945

100

GA

213

m134360

102

M136665

111

OVER007

300

m134360

0

M136665

300

ST303

997

M136554

20

m137073

977

3

Tuesday, March 28, 2017 3:41:09 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

5.0 PARTS LIST

QTY -011	QTY -013	QTY -015	Part Number	Description
X			D412-758-011	Bottom Mounted GPS Receiver Gimbal Mount
	X		D412-758-013	Top Mounted GPS Receiver Gimbal Mount
		X	D412-758-015	GPSMAP Top Mounted GPS Receiver Gimbal Mount
1			D3514-041	Bottom Mounted Gimbal Assembly
	1		D3514-043	Top Mounted Gimbal Assembly
		1	D3531-041	Bracket Assy.
	2	2	D2464-0066	Neoprene Seal
1	1	1	D3525-1	Placard
1			D3527-1	Support Arm
1			D3530-1	Base Plate
1			D3530-3	Mounting Plate
1	1		D3534-1	Doubler
	4	4	D3645-1	Washer
		3	AN525-10R9	Screw
	4	4	AN525-10R10	Screw
3			AN526-632R7	Screw (or MS35206-229)
3		4	NAS1149DN632J	Washer (Alternate p/n AN960JD6)
2	4	7	NAS1149D0363J	Washer (Alternate p/n AN960JD10)
3		4	MS21042L06	Nut
1		3	MS21042L3	Nut
4	4		MS24693-S27	Screw
1			MS27039-1-09	Screw
		4	MS24693-S29	Screw
		2	RAM-B-201U-A	Socket Arm, 1.75"
		2	RAM-B-202U	Round Plate Mount, Single 1" Ball
		1	RAM-B-217U	Round Plate Mount, Dual 1" Ball

• COPYRIGHT © 2010 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: D

Date: 12.08.10